



Dominion

DAM INSPECTION CHECKLIST POSSUM POINT POWER STATION POND ABC

INSPECTION DATE: 5/5/15

WEATHER: 66°F, A few clouds

INSPECTED BY: D. West, J. Marcell

Location/ Condition	(y/n)	Change (y/n)	Comments
Low Point, A dike*			
Flow	N	N	0852 hrs. Standing water along perimeter of pond
Erosion	N	N	new road. Standing water behind sandbags. Very slow seeping in front of sandbags.
Low Point, B dike*			
Flow	N	N	0857 hrs. No standing water. Sand bags and
Erosion	N	N	rip rap in place.
Outfall			
water surface El. (top of stoplogs to water)			0901 hrs. Standing water behind sand bagged area and behind concrete weir structure. 41 1/2". Slow seeping and dripping below 2X10, about 7' down. Standing stagnant water at discharge pipe. Does not appear to be discharging.

* See figure below.

Additional Comments (Note any changes observed along the embankment crest or downstream slope observed from the crest.): No rainfall event in last 72 hrs. * Standing water and wet at NE end of A pond, (area indicated by *). Standing water at the base of the slope between A & B pond.

LT 1500 , HT 0821

